



FURON[®] HP PFA 400 STRAIGHT TUBING PART NUMBER COMPARISON GUIDE

NEW Part Number	Previous Part Number	O.D.		I.D.		Wall Thickness		Tolerance		
		in	mm	in	mm	in	mm	in	mm	
Standard Wall										
FHI2ODHSFX	TSFP5.125063.HP-10	1/8	3.17	1/16	1.59	0.031	0.79	+/- 0.004	+/- 0.1	
FHI4OEHSFX	TSFP5.250156.HP-10	1/4	6.35	5/32	3.97	0.047	1.19			
FHI6OFHSFX	TSFP5.375250.HP-10	3/8	9.52	1/4	6.35	0.062	1.57	+/- 0.005	+/- 0.12	
FHI8OFHSFX	TSFP5.500375.HP-10	1/2	12.7	3/8	9.52					
FHI12OFHSFX	TSFP5.750625.HP-10	3/4	19.05	5/8	15.87					
FHI16OFHSFX	TSFP5.100875.HP-10	1	25.4	7/8	22.22					
FHI20OGHSFX	TSFP5.125110.HP-10	1-1/4	31.75	1.10	27.94	0.075	1.90	+/- 0.008	+/- 0.20	
FHM40OHHSFX	TCFHP.1575.086-10	1.575	40	1.403	35.64	0.086	2.18			
Heavy Wall										
FHI4OFHSFX	TSFP5.250125.HP-10	1/4	6.35	1/8	3.17	0.062	1.57	+/- 0.005	+/- 0.12	
FHI12OIHSFX	TSFP5.750-093.HP-10	3/4	19.05	0.564	14.33	0.093	2.36			
FHI16OIHSFX	TSFP5.1000-093.HP-10	1	25.4	0.814	20.68					
FHI20OIHSFX	TSFP5.1250-093.HP-10	1-1/4	31.75	1.064	27.03					
FHI24OIHSFX	TSFP5.1500-093.HP-10	1-1/2	38.1	1.314	33.38			+/- 0.008	+/- 0.20	
Thin Wall										
FHI4ODHSFX	TSFP5.250188.HP-10	1/4	6.35	3/16	4.76	0.031	0.79	+/- 0.003	+/- 0.08	
FHI6ODHSFX	TSFP5.375313.HP-10	3/8	9.52	5/16	7.94					
FHI8ODHSFX	TSFP5.500438.HP-10	1/2	12.7	7/16	11.11					
FHI12ODHSFX	TSFP5.750688.HP-10	3/4	19.05	11/16	17.46					

